

AD-DCW (Door Contacts)

1. Remove the battery insulator and set the dipswitches. Mount in desired location next to door or window.
2. Mount sensor that is wired to transmitter on edge of window or door gap with arrow pointing towards gap.
3. Mount free sensor on opposite side of gap with arrow pointing towards gap.

